





Article No.:	4010 0266 + 4010 0267	
Description:	Alteration of HP 342 to full capacity	
Date / Page:	12th September 2007 / 1 of 1	

Alteration to full ink capacity

The ink cartridges HP 342, HP 351, HP 110 has separating walls within the ink chambers (see Fig. 1a). After removing these separating walls by either cutting or breaking them out the full cartridge capacity can be utilised (see Fig. 1b). This creates a lower lying narrow space in the yellow ink chamber above the preceding nozzle chamber. This narrow space is bridged by a custom formed sponge (see Fig. 1c). Using this sponge the chamber will be completely filled. Samples are available on request.



1a) Top view onto an opened HP342 cartridge.

1b) Removed separating walls.

1c) Cross-section view of yellow ink chamber with sponge inserted.

New products for ink cartridges HP 342, HP351, HP110



Article No.: 4010 0266

Sponge for yellow ink chamber.



Article No.: 4010 0267

Sponge for the red and blue ink chamber, to alter a cartridge two sponges are required.

All brands mentioned in this document are trademarks of their respective owners. Only mentioned to identify